



ROADWORTHINESS ASSURANCE STANDARD (RAS)



AL HASHAR & COMPANY

SAFETY INSPECTION REPORT - HGV

Owner:	TRUCKOMAN NORTH L.L.C
Fleet Number:	—
Odometer reading	041
Current Uer (Ref Ind):	—
No. of PDO Spec.used	—
(For first use inspection only)	—

Vehicle type and Model:	TAOANO CRANE QR 500EX.
Registreation Number:	9436 - A K
Inspection Date:	01 - 11 - 17
Inspected At:	AL HASHAR & Co., AZAIBA
Contract Number:	—
Contact Holder (Ref Ind):	—

Part 1 : CHECK LIST FOR INSPECTION.

✓ - Pass x - Fail NA - Not Applicable.

No.		STATUS
1	Seat belts.	✓
2	Smoke emission.	✓
3	Road wheels and hubs.	✓
4	Tyres: size and type.	✓
5	Tyres: condition, pressure	✓
6	Side guards, under-run guards, bumpers.	✓
7	Spare wheel, jack, tools.	✗
8	Trailer coupling.	✗
9	Mudguards.	✓
10	Cabin mountings.	✓
11	Cabin doors.	✓
12	Cabin floor and steps.	✓
13	Seats.	✓
14	Bodywork: Load area, headboard fixed.	✓
15	Mirrors.	✓
16	Windscreen glass vision, 100mm crack maximum in swept area.	✓
17	Windscreen wipers, washers.	✓
18	Speedometer.	✓
19	Horn.	✓

AL HASHAR & CO. Muscat - Oman Tel.: 24595481	JAN			
BLACK TOP & GRADED ROADS	FEB			
INSP CERT. 227	MAR			
INSPECTION NO: BG: 23985	APR			
REG. NO.: 9436 - A K	MAY			
CONTRACT NO.: —	JUN			
OWNER: TRUCKOMAN NORTH L.L.C	JUL			
INSP DATE: 01 - 11 - 17	AUG			
NEXT INSP: 31 - 10 - 18	SEP			
INSPECTED BY:	OCT			
16	17	18	19	NOV
				DEC

		STATUS	DEFECT FOUND	RE -CHECKED
20	Driving Controls.	✓		
21	Tachograph or IVMS.	✗		
22	Steering wheel, column.	✓		
23	Pressure/Vaccum warning.	✓		
24	Pressure/Vaccum build up.	✓		
25	Mechanical brake levers.	✓		
26	Service brake pedal.	✓		
27	Service brake operation.	✓		
28	Hand brake control valves.	✓		
29	Chassis, subframe.	✓		
30	Electrical equipment wiring.	✓		
31	Engine & Transmission mountings.	✓		
32	Oil leaks.	✓		
33	Fuel tank(s) and system.	✓		
34	Exhaust.	✓		
35	Suspension.	✓		
36	Shock absorbers.	✓		
37	Axles, wheel bearings.	✓		
38	Steering assy: including tie rod ends.	✓		
39	Transmision.	✓		
40	Mechanical brake.	✓		
41	Brake actuators.	✓		
42	Brake system and components.	✓		
43	Rear markings.	✓		
44	Position lamps.	✓		
45	Reflectors.	✓		
46	Indicators.	✓		
47	Head lamp aim.	✓		
48	Head lamps.	✓		
49	Brake lights.	✓		
50	Service brakes.	✓		
51	Secondary brakes.	✓		
52	Parking brakes.	✓		
53	Reversing alarm.	✓		
54	High intensity rear lights.	✓		
55	Revolving lights.	✓		
56	A/C units.	✓		
57	Fire extinguisher on cab.	✓		
58	Fire extinguisher on load.	✓		
59	First aid kit.	✓		
60	Winch: General condition.	✓		
61	Slings.	✓		
62	Oil field head boards.	✗		
63	Speed limiter by <u>Road test</u>	✗		
64	Fluid levels.	✓		
65	Tippers: ram operation, oil leaks.	✗		
66	Tippers: hinge shaft and bearings.	✓		
67	Radio cassette operation.	✓		

HGV Continued....

		STATUS	DEFECT FOUND	RE -CHECKED
68	Fifth wheel assembly on Prime mover.			
69	Security of attachment of Fifth wheel- to Prime mover chassis.			
70	Maxi: Speed sticker to be stuck inside the cabin to be seen by the driver.			

For Tankers.

1	Colour code.			
2	PTO.			
3	Tank design.			

For Flammable / Hazardous substance Tanker.

1	Exhaust.			
2	Tyres.			
3	Isolation switch.			
4	Covered battery terminals.			
5	Substance collect / discharge valve location.			
6	Wiring protected by solid draw tubes.			
7	Fire resistant shield.			
8	earthing while discharge & charge.			
9	Vaccum relief valve.			
10	Certificate of compliance.			

Part 2: Defect information, must be attached as the next page, and signed off by the vehicle inspector.

Name of inspector-

Signature-



Insp Cert. 227



Attach this to Part 1 of the Safety Inspection Report

PART 2: DEFECT INFORMATION

In Check No. column, use checklist number from list above. Repairs to be signed-off by repair workshop supervisor.


If many defects, continue on blank page and attach to this report.

Check No.	Defect details	Action taken on Defect	Signed

" I confirm that the above defects, if any were found, have been rectified satisfactorily.
The vehicle is now in proper roadworthy condition"



Name of Vehicle Inspector


Signature of Vehicle Inspector



Check for information on attached sheets

