الشركة الفنية لخدمات السلامة ش.م.م

SAFETY *technical* SERVICES CO. LTD.

LEEA

# MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|---|---|
| **Date of Thorough Examination:** 17/01/2019 | **Report number:** MA/39312/19/01/03 | **Job no:** 39312 |

| | |
|---|---|
| **Name and Address of owner for whom the thorough examination was made:**<br><br>**PREMIER LOGISTICS MUSCAT**<br>**SULTANATE OF OMAN** | **Address of premises at which the examination was made:**<br>**FAHUD (HOIST-52)** |

**Method: WET** **Material: Carbon Steel** **Test temperature: Ambient**
**Surface Condition: Acceptable** **Equipment: Permanent magnet Yoke**

**Area Inspected ( tick the appropriate box):**

☑ Weldment areas ☑ Stress Areas ☐ Full Body ☐ Others

| | |
|---|---|
| **WHITE CONTRAST PAINT: Magnavis WCP** | **MAGNETISING METHOD: Wet suspension black ink** |
| **BLACK MAGNETIC INK: Magnaflux 7HF** | **ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1** |

**Description and identification of the equipment:**

**<u>FORK MPI</u>**

**Forklift Reg. No. : 1602 BA**

**Forklift Fleet No. : PLM 1530**

**Qty: 1no**

Date of Last MPI/ Cert No( If any): N/A

**Result of the above test :**

**MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION**

| | | |
|---|---|---|
| **Inspected by, Name & Signature :**<br><br>**Qualification : ASNT L2** | **Infanso Oswin** | **Latest date by which next MPI must be carried out:**<br><br>**16/01/2020** |
| **Name and address of employer of persons making and authenticating this report:**<br><br>**SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT.**<br>**lifting@safetyoman.com** | | CERTIFIED |