

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 24/06/2023	Report number: MP/51271/23/06/93	Job no: 51271
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><u>Forklift Details:</u></p> <p>Make : Caterpillar</p> <p>Model no. : DP 50 NT</p> <p>Serial no.: CT-28C-50371</p> <p>Owner ID : TO-2530</p> <p>Reg. No. : 5156 RA</p>		
<p><u>Fork Details:</u></p> <p>Fork ID : 1509300 & 1501394A</p> <p>Qty: 1 pair</p>		
Date of Last MPI/ Cert No (If any): 15/07/2023;MP/48942/03		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

