



الشركة الفنية لخدمات السلامة ش.م.م  
SAFETY *technical* SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 07/12/2018	Report number: A/38650/18/12/04	Job no: 38650
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN (SOUTH) SULTANATE OF OMAN	Address of premises at which the examination was made:  MARMUL	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FORKS OF A FORKLIFT</u>		
<u>Forklift Details:</u> Make : Caterpillar Model no. : 930 K Serial no.: 00362 Owner ID : TO 2531 Reg. No. : 5157 RA		
<u>Fork Details:</u> Fork ID : 1997393 – L1 & 1997394-L1  Qty: 1pair		
Date of Last MPI/ Cert No( If any): 18/12/2017 ; A/36259/17/12/4		
<u>Result of the above test :</u>  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature :  Qualification : ASNT L2	Mohammed Anaz 	Latest date by which next MPI must be carried out:  06/12/2019
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		