



الشركة الفنية لخدمات السلامة ش.م.م  
**SAFETY *technical* SERVICES CO. LTD.**



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 17/03/2019	Report number: MA/39822/19/03/07	Job no: 39822
Name and Address of owner for whom the thorough examination was made: <b>TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN</b>		Address of premises at which the examination was made: <b>JIFFNAIN</b>
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <b>MAIN HOOK OF A ROUGH TERRAIN CRANE</b>		
<u>Crane Details:</u> Make : Grove ; 2012 Model no. : RT 530E-2 Serial no. : 253577 Reg. No. : 6228 YR Owner ID no. : PLM-1482		
<u>Hook Details:</u> SWL : 30 t Hook Cert. No.: 57792		
Date of Last MPI / Cert. No. (if any) :02/04/2018 ; O/37007		
Result of the above test : <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature : Qualification : ASNT L2	Malik Mohammed 	Latest date by which next MPI must be carried out: 16/03/2020
Name and address of employer of persons making and authenticating this report: <b>SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT.</b> <a href="mailto:lifting@safetysoman.com">lifting@safetysoman.com</a>		