



الشركة الفنية لخدمات السلامة ش.م.م  
**SAFETY *technical* SERVICES CO. LTD.**



**MAGNETIC PARTICLE INSPECTION REPORT**

Date of Through Examination: 25/08/2017	Report number: MP/35191/17/08/02	Job no: 35191
Name and Address of the Owner of the Equipment  PREMIER LOGISTICS MUSCAT LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  YIBAL
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>MAIN &amp; AUX CRANE HOOK</u>		
<u>Crane Details:</u>  Make : TADANO Serial no. : 541085 Owner ID no. : PLM-1491		
<u>Hook Details:</u>  Main Hook Serial no. : 4327 Aux Hook Serial no. : 4319 A		
Date of Last MPI / Cert. No. (if any) : Nil		
<u>Result of the above test :</u>  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature :  Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out:  24/08/2018
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		