


## MAGNETIC PARTICAL INSPECTION REPORT (MPI)

### FORK

CERTIFICATE NUMBER:		<b>SAG-INS-2023-221-6-MS</b>	
CLIENT NAME:		<b>TRUCKOMAN EQUIPMENT RENTAL LLC, SULTANATE OF OMAN.</b>	
DATE OF INSPECTION:		<b>20.03.2023</b>	
NEXT INSPECTION DATE		<b>19.09.2023</b>	
DISCRIPTION OF MATERIAL INSPECTED:		<b>FORK</b>	
ITEM SR/NO/ID NO/STICKER NUMBER:		<b>LH6000/600</b>	
REG NUMBER		<b>775 MS</b>	
DETAILS OF PRVIOUS INSPECTION:		<b>NOT APPLICABLE NEW EQUIPMENT</b>	
PLACE OF INSPECTION:		<b>GHALA</b>	
CODE / STANDARD:		<b>ASME SEC V/AWS D1.1</b>	
ACCEPTANCE CRITERIA:		<b>AWS D1.1PARTC CLAUSE 6.10</b>	
ITEM LOCATION/DETAILS:		<b>LOAD BEARING SURFACE</b>	
Equipment:	EECIFLUX, MODEL PY2, SR NO PY044CM	Surface condition:	Cleaned at ambient temp
Black magnetic ink:	MR76S (765/3112)	Illumination:	Day light
White contrast paint:	MR72 (72/3002)	Examination technique:	Wet condition
Equipment calibration:	15.02.2023 Certno:GIS/23/3340-05	Sensitivity:	BC Strip
<b>OBSERVATION AND RESULT:</b>		<b>DIGITAL PHOTO:</b>	
1. VISUAL INSPECTION CARRIED OUT FOUND SATISFACTORY. 2. MPI TEST FOR LOAD BEARING SURFACE OF THE ITEM CARRIED OUT, NO IDICATION OF FAILURE FOUND <b>TEST RESULT ACCEPTABLE.</b>			

Name and Qualification of the authorized Person:	 	Name and Qualification of Inspection Engineer:
Marwan Al Busaidi,		 Rajendra Jambukar

M/s SAG ALSAHLRA TRADING AND CONTRACTING, Zaid building, Off No:403, Ghala Industrial, PO BOX No:124, PC:418, Muscat Sultanate of Oman Tel:+968 24033282, Email [inspection@sag-alsahra.com](mailto:inspection@sag-alsahra.com) Web: [www.alsahra.com](http://www.alsahra.com)

