

**CERTIFICATE OF THROUGH EXAMINATION OF
WHEEL LOADER**

CERTIFICATE NUMBER: STICKER NUMBER:	SAG-INS-2023-221-5-MS
CLIENT NAME:	TRUCKOMAN EQUIPMENT RENTAL LLC, SULTANATE OF OMAN.
DATE OF INSPECTION:	20.03.2023
NEXT INSPECTION DATE	19.09.2023
DETAILS OF PRVIOUS INSPECTION:	NOT APPLICABLE NEW EQUIPMENT
PLACE OF INSPECTION:	GHALA
CODE / STANDARD:	BSEN474-4/BS ISO 2330:2002
DISCRIPTION OF MATERIAL/EQUIPMENT INSPECTED:	DIESEL POWERED HYDRAULIC WHEEL LOADER
ITEM SR/NO/ID NO/REG NO / OWNER NO:	775 MS
MODEL AND SERIAL NUMBER	CLG870H / CLG870HZNEL785657
MAKE AND YEAR OF MANUFACTURING:	LIUGONG 2023
INSPECTION DETAILS:	THROUGH VISUAL AND FUNCTIONAL TEST CAAEIED OUT AND EQUIPMENT FOUND FIT FOR USE.


This is to certify that the under signed, a competent representative did attend to examine this equipment to ascertain the safe working condition of the equipment. At the time of examination indicated, the said equipment has no indigenous injury or sighted deformation. The equipment is safe for its intended use within the limits specified, provided there is a continuous maintenance applied and qualified operators employed

Name and Qualification of the Inspector:		Name and Qualification of Authorized person
Marwan Al Busaidi		Rajendra Jambukar

MAGNETIC PARTICAL INSPECTION REPORT (MPI)

LIFTING ARM

CERTIFICATE NUMBER:		SAG-INS-2023-221-7-MS	
CLIENT NAME:		TRUCKOMAN EQUIPMENT RENTAL LLC, SULTANATE OF OMAN.	
DATE OF INSPECTION:		20.03.2023	
NEXT INSPECTION DATE		19.09.2023	
DESCRIPTION OF MATERIAL INSPECTED:		LIFTING ARM WITH HOOK	
ITEM SR/NO/ID NO/STICKER NUMBER:		CLG870HZENL785657	
REG NUMBER		775 MS	
DETAILS OF PRVIOUS INSPECTION:		NOT APPLICABLE NEW EQUIPMENT	
PLACE OF INSPECTION:		GHALA	
CODE / STANDARD:		ASME SEC V/AWS D1.1	
ACCEPTANCE CRITERIA:		AWS D1.1PARTC CLAUSE 6.10	
ITEM LOCATION/DETAILS:		LOAD BEARING SURFACE	
Equipment:	EECIFLUX, MODEL PY2, SR NO PY044CM	Surface condition:	Cleaned at ambient temp
Black magnetic ink:	MR76S (765/3112)	Illumination:	Day light
White contrast paint:	MR72 (72/3002)	Examination technique:	Wet condition
Equipment calibration:	15.02.2023 Certno:GIS/23/3340-05	Sensitivity:	BC Strip
OBSERVATION AND RESULT:		DIGITAL PHOTO:	
1. VISUAL INSPECTION CARRIED OUT FOUND SATISFACTORY. 2. MPI TEST FOR LOAD BEARING SURFACE OF THE ITEM CARRIED OUT, NO INDICATION OF FAILURE FOUND TEST RESULT ACCEPTABLE.			

Name and Qualification of the authorized Person:		Name and Qualification of Inspection Engineer:
 Marwan Al Busaidi,		 Rajendra Jambukar

MAGNETIC PARTICAL INSPECTION REPORT (MPI)

BUCKET

CERTIFICATE NUMBER:		SAG-INS-2023-221-8-MS	
CLIENT NAME:		TRUCKOMAN EQUIPMENT RENTAL LLC, SULTANATE OF OMAN.	
DATE OF INSPECTION:		20.03.2023	
NEXT INSPECTION DATE		19.09.2023	
DESCRIPTION OF MATERIAL INSPECTED:		BUCKET	
ITEM SR/NO/ID NO/STICKER NUMBER:		CLG870HZENL785657	
REG NUMBER		775 MS	
DETAILS OF PRVIOUS INSPECTION:		NOT APPLICABLE NEW EQUIPMENT	
PLACE OF INSPECTION:		GHALA	
CODE / STANDARD:		ASME SEC V/AWS D1.1	
ACCEPTANCE CRITERIA:		AWS D1.1PARTC CLAUSE 6.10	
ITEM LOCATION/DETAILS:		LOAD BEARING SURFACE	
Equipment:	EECIFLUX, MODEL PY2, SR NO PY044CM	Surface condition:	Cleaned at ambient temp
Black magnetic ink:	MR76S (765/3112)	Illumination:	Day light
White contrast paint:	MR72 (72/3002)	Examination technique:	Wet condition
Equipment calibration:	15.02.2023 Certno:GIS/23/3340-05	Sensitivity:	BC Strip
OBSERVATION AND RESULT:		DIGITAL PHOTO:	
1. VISUAL INSPECTION CARRIED OUT FOUND SATISFACTORY. 2. MPI TEST FOR LOAD BEARING SURFACE OF THE ITEM CARRIED OUT, NO IDICATION OF FAILURE FOUND TEST RESULT ACCEPTABLE.			

Name and Qualification of the authorized Person:	 C/L No: 110001 Sahara of Oman	Name and Qualification of Inspection Engineer:
 Marwan Al Busaidi,		 Rajendra Jambukar