


MAGNETIC PARTICAL INSPECTION REPORT (MPI)

FORK

CERTIFICATE NUMBER:	SAG-INS-2023-221-2-MS		
CLIENT NAME:	TRUCKOMAN EQUIPMENT RENTAL LLC, SULTANATE OF OMAN.		
DATE OF INSPECTION:	20.03.2023		
NEXT INSPECTION DATE	19.09.2023		
DESCRIPTION OF MATERIAL INSPECTED:	FORK		
ITEM SR/NO/ID NO/STICKER NUMBER:	LH6000/600		
REG NUMBER	3558 BM		
DETAILS OF PRVIOUS INSPECTION:	NOT APPLICABLE NEW EQUIPMENT		
PLACE OF INSPECTION:	GHALA		
CODE / STANDARD:	ASME SEC V/AWS D1.1		
ACCEPTANCE CRITERIA:	AWS D1.1PARTC CLAUSE 6.10		
ITEM LOCATION/DETAILS:	LOAD BEARING SURFACE		
Equipment:	EECIFLUX, MODEL PY2, SR NO PY044CM	Surface condition:	Cleaned at ambient temp
Black magnetic ink:	MR76S (765/3112)	Illumination:	Day light
White contrast paint:	MR72 (72/3002)	Examination technique:	Wet condition
Equipment calibration:	15.02.2023 Certno:GIS/23/3340-05	Sensitivity:	BC Strip
OBSERVATION AND RESULT:	<p>1. VISUAL INSPECTION CARRIED OUT FOUND SATISFACTORY.</p> <p>2. MPI TEST FOR LOAD BEARING SURFACE OF THE ITEM CARRIED OUT, NO IDICATION OF FAILURE FOUND TEST RESULT ACCEPTABLE.</p>		
	DIGITAL PHOTO: 		

Name and Qualification of the authorized Person:  Marwan Al Busaidi,		Name and Qualification of Inspection Engineer:  Rajendra Jambukar
---	---	---