






الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/03/2026	Report number: GE/7206/26/03/02	Job no: 7206
Name and Address of the Owner of the Equipment TRUCKOMAN EQUIPMENT RENTAL LLC Sultanate of Oman	Address of premises at which the examination was made: SLB FRAC 12 – BURHAN SITE	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnaflux WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>WHEEL LOADER FORK ATTACHMENT</u> Serial No: LH6000/600 Fork Tines Length: 1820 mm Mounted in Fleet No.: TER 1539 Mounted in Reg No: 3558 BM		
Date of Last MPI/ Cert No(If any): 01/03/2025 / MN/1569/25/03/43		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : KOSHY MATHEW Qualification : ASNT LEVEL 2		Latest date by which next MPI must be carried out: 01/03/2027
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		




الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/03/2026	Report number: GE/7206/26/03/03	Job no: 7206
Name and Address of the Owner of the Equipment TRUCKOMAN EQUIPMENT RENTAL LLC Sultanate of Oman	Address of premises at which the examination was made: SLB FRAC 12 – BURHAN SITE	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnaflux WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: WHEEL LOADER BUCKET ATTACHMENT Part No.: GD2211425 Serial No: 38Y1105 Capacity: 4.2 m3 Mounted in Fleet No.: TER 1539 Mounted in Reg No: 3558 BM		
		
Date of Last MPI/ Cert No(If any): 05/03/2024 / K/0776/24/03/04		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : KOSHY MATHEW Qualification : ASNT LEVEL 2		Latest date by which next MPI must be carried out: 01/03/2027
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/03/2026	Report number: GE/7206/26/03/04	Job no: 7206
Name and Address of the Owner of the Equipment TRUCKOMAN EQUIPMENT RENTAL LLC Sultanate of Oman	Address of premises at which the examination was made: SLB FRAC 12 – BURHAN SITE	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnaflux WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>WHEEL LOADER TELESCOPIC MATERIAL HANDLING ARM ATTACHMENT</u> Part No.: GD2211464 Serial No: 4300633X0 Mounted in Fleet No.: TER 1539 Mounted in Reg No: 3558 BM Date of Last MPI/ Cert No(If any): 05/03/2024 / K/0776/24/03/03		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : KOSHY MATHEW Qualification : ASNT LEVEL 2		Latest date by which next MPI must be carried out: 01/03/2027
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		