



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|--|--|
| Date of Thorough Examination: 05/11/2023 | Report number: MP/53019/23/11/01 | Job no: 53019 |
| Name and Address of owner for whom the thorough examination was made: TRUCKOMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN | Address of premises at which the examination was made: AZAIBA | |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others [TOP SURFACE ONLY] | | |
| WHITE CONTRAST PAINT: MAGNAVIS WCP | MAGNETISING METHOD: WET SUSPENSION BLACK INK | |
| BLACK MAGNETIC INK: MAGNAFLUX 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>FORK HEEL & WELDS</u> Fork Serial No: T20C-61809 Qty: 1 no Date of Last MPI/ Cert No (If any): NA | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by, Name & Signature : MADHU PILLAI Qualification: ASNT L2 | | Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | | |

