

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 12/09/2023	Report number: MP/51295/23/09/05	Job no: 51295
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL		Address of premises at which the examination was made: JIFANAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
<b>FIFTH WHEEL</b> MAKE : JOST TYPE: JSK39DV1-46 SERIAL NO: 33DD0500472C REG NO: 5575 RH FLEET NO:TER 1091  QTY: 1 NOS DATE OF LAST MPI/CERT NO: N/A		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : MADHU PILLAI		Latest date by which next MPI must be carried out: 11/09/2024
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

