

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 17/10/2025	Report number: VG/5343/25/10/08	Job no: 5343
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL LLC		Address of premises at which the examination was made: ADAM
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	

FIFTH WHEEL

MAKE: JOST

TYPE: JSK39DV1-46

SERIAL NO: 33DD0100159C

REG NO: 4130 MB

FLEET NO: TER 1092

QTY: 1 NOS

DATE OF LAST MPI/CERT NO: MN/1139/24/11/09

Result of the above test:

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION

Inspected by, Name & Signature: VIGNESH CT		Latest date by which next MPI must be carried out: 16/04/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

