



<b>ASTRON GROUP</b>	<b>MAGNETIC PARTICLE INSPECTION REPORT</b>	
-------------------------	--	--

Client: TRUCKOMAN	Report No: AST-MP19-054-23
Contractor: None	Date of Inspection: 09.09.2023
Project: N/A	Reg. No: VIN: LFCNR54D3P3001241
Site / Location: GHALA	Procedure No: T3-TEP-NDE-101, Rev 3
Serial No. RC0090CD0693	Acceptance Criteria: AWS D1.1.

<b>Component Description: Hook</b>			
Material: Carbon Steel		Construction Code: None	
Equipment Type: YM5 YOKE		Method:	Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Fluorescent <input type="checkbox"/>
Equipment Sl. No.: 18152		PWHT:	N/A <input checked="" type="checkbox"/> Before <input type="checkbox"/> After <input type="checkbox"/>
Lifting Capacity: 18.0 Kg		Viewing Condition: Day Light	
Leg Spacing: 1" to 6"		Surface Condition: As welded & cleaned	
Contrast Paint: 161003		Surface Temp: 28 Deg C	
Magnetic Ink: 160601		Sensitivity: BC strip	

Sl. No.	ITEM	QTY	SERIAL NO.	Observation	Result
1	Main Hook 90T	01	HCZ2390050	NO RELEVANT INDICATION WAS OBSERVED DURING THE INSPECTION.	ACCEPTABLE
2	Aux Hook 8T	01	QZG8.20 YM2023052510		

	
--	--

<b>Astron Quality &amp; Calibration LLC</b>	<b>Client / Contractor</b>
Signature: 	Next Insp. Date: 08 <sup>th</sup> Sept 2024
Name: Ajmal Ibrahim	
Qualification: ASNT LEVEL-2	
Date: 09 <sup>th</sup> Sept 2023	



Rev No. 3

T3-TEP-NDE-101

**ASTRON QUALITY AND CALIBRATION LLC**

7th Floor, Office No.72, Building No.638, Azaiba North, Muscat,  
Sultanate of Oman.T: +968 24498006, F: +968 24498226,  
Email: [astron-oman@astrongroup.com](mailto:astron-oman@astrongroup.com), Web: [www.astrongroup.com](http://www.astrongroup.com)

