



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 28/12/2025	Report number: MN/5692/25/12/08	Job no: 5692
Name and Address of owner for whom the thorough examination was made: TRUCKOMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN	Address of premises at which the examination was made: ADAM	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☒ Weldment areas ☒ Stress Areas ☐ Full Body ☐ Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: <u>KING PIN AND FILLET WELD</u> Make: JOST (3.5") Type: KZ 14 SL NO: ZTLB0510190000004 Trailer Reg: 7024 RH Fleet No: TER 1966 [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1 no Date of Last MPI/ Cert No (If any): VG/4241/25/07/06		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature: MIDHUN CS		Latest date by which next MPI must be carried out: 27/06/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		