

### MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 06/09/2025	Report number: MN/5319/25/09/02	Job no: 5319
Name and Address of owner for whom the thorough examination was made:  TRUCKOMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made:  FAHUD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FIFTH WHEEL</u>  MAKE: JOST ID NO: 33790500884C TYPE: JSK39DV1-30 FLEET NO: TER 1103 TRAILER REG: 9713 MH  Qty: 1nos		
Date of Last MPI/ Cert No(if any): <b>MN/0389/24/09/02, 28/09/2024</b>		
Result of the above test:  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature: MIDHUN C S		Latest date by which next MPI must be carried out: 05/03/2026
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		