



**TA'AZEEZ ENTERPRISES LLC**  
 Po Box: 23, P.O: 103-AL Qurum North AL Ghoubra- Bowsher  
 Sultanate Of Oman

### MAGNETIC PARTICLE INSPECTION REPORT

<b>Company Name and Address</b>		<b>Inspection Location</b>	
TRUCK OMAN EQUIPMENT RENTAL LLC		GHALA	
<b>Certificate Number:</b> MM.0268.11.23.16.03	<b>Job No:</b> 0268		
<b>Date of Thorough Examination:</b> 16.11.2023	<b>Issue Date:</b> 16.11.2023		
<b>Date of Previous MPI/ cert no:</b> NEW	<b>Date of Next Examination:</b> After One Year As Per Clients Requirements Or At The Discretion Of Inspector		
<b>Description and Identification of the equipment: FORK MPI</b>			
Make: LIUGONG / 2024  Reg No: 8372 AK  Fork Serial No: 20230907001			
<b>Area Inspected ( tick the appropriate box):</b>			
<input type="checkbox"/> Weldment areas	<input checked="" type="checkbox"/> Stress Areas	<input type="checkbox"/> Full Body	<input type="checkbox"/> Others ( top surface )
WHITE CONTRAST PAINT: MAGNAVIS WCP		MAGNETISING METHOD: WET SUSPENSION BLACK INK	
BLACK MAGNETIC INK: MAGNAFLUX 7HF		ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
TEST METHOD: WET		MATERIAL: CARBON STEEL	
TEST TEMPERATURE: AMBIENT		SURFACE CONDITION: ACCEPTABLE	
TEST EQUIPMENT: PERMANENT MAGNET YOKE			
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION			

Inspected by: MALIK MOHAMMED  Qualifications: ASNT LEVEL II  Signature:   Date: 16.11.2023	Company Stamp  
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------

If any Alteration/Major Repair is made, this certificate is rendered invalid.  
 This is to confirm that the item listed above was examined by the undersigned competent representative in compliance with the aforementioned standard. The aforementioned objects were found to be free of faults, deformations, and other problems at the time of inspection. The equipment is suitable for its intended use within the permitted limits, and at the time of inspection, it was determined to be suitable for continued use, provided that continuous maintenance is applied, qualified operators are employed, and our comments and recommendations are put into practice.



**TA'AZEEZ ENTERPRISES LLC**

Po Box: 23, P.O. 103-AL Qurum North AL Ghoubra- Bowsher  
Sultanate Of Oman

### MAGNETIC PARTICLE INSPECTION REPORT

<b>Company Name and Address</b>		<b>Inspection Location</b>
<b>TRUCK OMAN EQUIPMENT RENTAL LLC</b>		<b>GHALA</b>
<b>Certificate Number:</b> <b>MM.0268.11.23.16.02</b>		<b>Job No:</b> <b>0268</b>
<b>Date of Thorough Examination:</b> <b>16.11.2023</b>		<b>Issue Date:</b> <b>16.11.2023</b>
<b>Date of Previous Examination/ Cert No:</b> <b>NEW</b>		<b>Date of Next Examination:</b> <b>After One Year As Per Clients Requirements Or At The Discretion Of Inspector</b>
<b>Description and identification of the equipment: BUCKET MPI</b>		
<b>Make:</b> LIUGONG / 2024 <b>Reg No:</b> 8372 AK <b>Bucket Serial No:</b> GD2307085		
<b>Area Inspected ( tick the appropriate box):</b>		
<input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas		<input type="checkbox"/> Full Body <input type="checkbox"/> Others ( top surface )
<b>WHITE CONTRAST PAINT:</b> MAGNAVIS WCP		<b>MAGNETISING METHOD:</b> WET SUSPENSION BLACK INK
<b>BLACK MAGNETIC INK:</b> MAGNAFLUX 7HF		<b>ACCEPTANCE CODE:</b> ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
<b>TEST METHOD:</b> WET		<b>MATERIAL:</b> CARBON STEEL
<b>TEST TEMPERATURE:</b> AMBIENT		<b>SURFACE CONDITION:</b> ACCEPTABLE
<b>TEST EQUIPMENT:</b> PERMANENT MAGNET YOKE		
<b>Result of the above test :</b> <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

<b>Inspected by :</b> MALIK MOHAMMED <b>Qualifications:</b> ASNT LEVEL II <b>Signature:</b>  <b>Date:</b> 16.11.2023	<b>Company Stamp</b> 
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------

<b>If any Alteration/Major Repair is made, this certificate is rendered invalid.</b> <b>This is to confirm that the item listed above was examined by the undersigned competent representative in compliance with the aforementioned standard. The aforementioned objects were found to be free of faults, deformations, and other problems at the time of inspection. The equipment is suitable for its intended use within the permitted limits, and at the time of inspection, it was determined to be suitable for continued use, provided that continuous maintenance is applied, qualified operators are employed, and our comments and recommendations are put into practice.</b>
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------



**MAGNETIC PARTICLE INSPECTION REPORT**

<b>Company Name and Address</b>		<b>Inspection Location</b>
TRUCK OMAN EQUIPMENT RENTAL LLC		GHALA
<b>Certificate Number:</b> MM.0268.11.23.16.04		<b>Job No:</b> 0268
<b>Date of Thorough Examination:</b> 16.11.2023		<b>Issue Date:</b> 16.11.2023
<b>Date of Previous MPI/ cert no:</b> NEW		<b>Date of Next Examination:</b> After One Year As Per Clients Requirements Or At The Discretion Of Inspector
<b>Description and identification of the equipment: JIB MPI</b>		
Make: LIUGONG / 2024  Reg No: 8372 AK  Arm Serial No: 20230907001		
<b>Area Inspected ( tick the appropriate box):</b>		
<input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas		<input type="checkbox"/> Full Body <input type="checkbox"/> Others ( top surface )
WHITE CONTRAST PAINT: MAGNAVIS WCP		MAGNETISING METHOD: WET SUSPENSION BLACK INK
BLACK MAGNETIC INK: MAGNAFLUX 7HF		ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
TEST METHOD: WET		MATERIAL: CARBON STEEL
TEST TEMPERATURE: AMBIENT		SURFACE CONDITION: ACCEPTABLE
TEST EQUIPMENT: PERMANENT MAGNET YOKE		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by : MALIK MOHAMMED  Qualifications: ASNT LEVEL II  Signature:   Date: 16.11.2023	Company Stamp
	

If any Alteration/Major Repair is made, this certificate is rendered invalid.  
 This is to confirm that the item listed above was examined by the undersigned competent representative in compliance with the aforementioned standard. The aforementioned objects were found to be free of faults, deformations, and other problems at the time of inspection. The equipment is suitable for its intended use within the permitted limits, and at the time of inspection, it was determined to be suitable for continued use, provided that continuous maintenance is applied, qualified operators are employed, and our comments and recommendations are put into practice.