HI-TECH
التكنولوجيا المتطورة لخدمات الفحص ش.م.م
HI-TECH INSPECTION SERVICES L.L.C.

**HI-TECH INSPECTION SERVICES L.L.C,**
**P.O.BOX 141, AL RUSAYAL, P.C. 124,**
**SULTANATE OF OMAN**
**Phone: (+968) 24449092 | 24446444 | 24449010 | 24446414**
**www.hitechoman.net Email: admin@hitechoman.net**

# MAGNETIC PARTICLE EXAMINATION REPORT

| | |
|---|---|
| Date of Examination: **17/01/2026** | Report No: **HITECH/TJN-2025-467/MT-147** |
| Client**: M/S. TRUCKOMAN EQUIPMENT RENTAL LLC, OMAN** | Contractor: **N/A** |
| Project: **N/A** | Location: **NIZWA,SULTANATE OF OMAN** |
| Procedure No. & Rev. No.: **HITECH-TPI-P-T-253-MT-14** | Referencing Code / Specification: **ASME E709 /AWS D1.1** |
| Acceptance Criteria: **AWS D1.1** | Material: **N/A** |

| | | |
|---|---|---|
| Surface Condition: **Acceptable** | Surface Temperature: **Ambient** | PWHT: **N/A** |
| Method: ☑ Wet ☑ Visible ☐ Dry ☐ Fluorescent | Technique: ☑ Continuous ☐ Residual | Magnetization: ☑ Longitudinal ☐ Circular |
| Equipment Type: **Permanent Yoke** | Equipment Sr. No: **GAMMATEC 00836** | Cal. Validity: **Prior to Job** |
| Type of Current: **N/A** | Lifting Power of Yoke: **18.1 Kg** | Sensitivity: ☑ Burmah Strip ☐ Pie Gauge **III Lines Visible** |
| Source of Light: **Day light** | Light Intensity: **≥ 1000 lux min** | |
| **Consumables: MAKE: MAGNAFLUX** | | |
| Cleaner: **MAGNAFLUX SKC-S**<br>Batch No: **240706 BBE**<br>Validity**: JULY-2027** | White contrast: **MAGNAFLUX WCP-2**<br>Batch No: **240702 BBE**<br>Validity: **JULY-2027** | Magnetic Ink: **MAGNAFLUX 7 HF**<br>Batch No: **240705 BBE**<br>Validity: **JULY-2027** |

| Item Description/Line No./ Drawing No. | Weld No | Welder No | Size | Sch. / WT | Observation (Map or Record of Indication) | Result (Acc./Rej.) |
|---|---|---|---|---|---|---|
| **REGISTRATION NO & OWNER ID NO:- 7989 LA-TER 1554 (MAKE: MAXTON,YOM:2023)** | | | | | | |
| **FORKS SL NO: 1Y2306038 (L) & 2Y2306038 (R) (QTY-01 PAIR)** | **N/A** | **N/A** | **N/A** | **N/A** | **NO RELEVANT INDICATION OBSERVED** | **ACCEPTABLE** |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

**"MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION"**

| | |
|---|---|
| **LATEST DATE BY WHICH NEXT MPI MUST BE CARRIED OUT:** | **16/01/2027** |

| **Hi-Tech Inspection Services LLC** | **Contractor** | **Client/ TPI /AI** |
|---|---|---|
| Signature: | Signature: | Signature: |
| Name: **ANSON D'COSTA**<br>Qualification: **MPT Level II** | Name: | Name: |
| Date: **17/01/2026** | Date: | Date |