



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 11/09/2018	Report number: MP/37744/18/09/04	Job no: 37744
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FORK HEEL & FORK HOLD BRACKET WELDED AREA</u>		
Owner ID No. : TO-2527		
Reg. No. : 5096 WK		
Fork Dimension : 1500mm x 750mm x 150mm (LxHxW)		
Qty: 1pair		
Date of Last MPI/ Cert No(If any): 27/09/2017 ; V/35391/17/09/53		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out: 10/09/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		