



**AN ISO/IEC 17020 ACCREDITED INSPECTION BODY**

**CERTIFICATE OF THOROUGH EXAMINATION AND TEST OF FORKLIFT**

**Job Card No: 5209**

**Date of Inspection: 11.09.2025**

**Certificate No: AT5209.25.09.01**

**Starting Time of Inspection: 11:00 AM**

Name and Address of the Owner:	TRUCK OMAN EQUIPMENT RENTAL	
Maker & Date of Manufacture:	MAXTON & 2023	
Place of Inspection:	RIMA	
Ref. Standard:	ISO22915-2 /BS EN 1459/SP2275	
Registration No. & Owner No.:	5083 LB & TER 1561	
Model No. and Serial No.:	CPCD70-XRW14 & 18BC08643	
Running hours:	1104.0 Hrs	
Manufacturer 's documentation:	IN SERVICES EQUIPMENT	
Date of Previous inspection / cert no:	20/03/2025 (K/3827/25/03/01)	
Date of Next inspection:	10.03.2026	
Date of Previous load test / cert no:	20/03/2025 (K/3827/25/03/01)	
Date of Next load test:	19.03.2026	
Availability of operations manual in cabin:	AVAILABLE	
Availability of daily check report:	AVAILABLE	
Description of Forklift:	Diesel powered hydraulic counter balanced forklift with side shifter SWL:7000 kgs 600 mm load center,	
<b>Test carried out according to tabulated co</b>		
Description of test: Visual inspection, Functional test & Performance test carried out.  Load Test is carried out as per a tabulated column.  Load cell used: Yes  Calibration certificate: DCML /36642-2/2023  Max. Lifting Height: 4000 mm  Fork S/N: Y2307507 & 2311126K(PAIR) Hydraulic creep: Nil	Test load applied In kgs	S.W.L In kgs
	7000 kg	7000 kg
<b>Conclusion: Fit for its intended use at the time of inspection. / Refer to checklist- Annexure of certificate</b>		
<i>This certificate becomes invalid if any Alteration/Major Repair and modification is done.</i>		
This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.		

Verified by, Name &Signature: Infanso Oswin

Inspected by, Name & Signature: Anoop Thankachan



**Annexure of certificate of test & thorough examination of forklift**

**Job Card No: 5209**

**Date of Inspection: 11.09.2025**

**Certificate No: AT5209.25.09.01**

**Starting Time of Inspection: 11:00 AM**

Status Legend: S- Satisfactory		NA-Not applicable		F-Findings	CF-Critical Findings	
No.	Description	Status	No.	Description		Status
1	Operations Manual/Catalogue	S	17	All gauges in cab		S
2	Monthly Inspection record	S	18	Overhead & foot guard		S
3	Maintenance records	S	19	Exhaust system		S
4	OEM Specification plate, (capacity)	S	20	Side shifting function (if applicable)		S
5	Tires, rims, wheel bolts and axles	S	21	Horn, reverse alarm, rotating warning light		S
6	Masts and Back rest, carriage	S	22	Lights & indicators		S
7	Forks and its extensions, slide end stopper, locks	S	23	Seat and seat belts		S
8	Load chain and its assemblies	S	24	Parking brake and foot brake function		S
9	Side rollers and roll over cage	S	25	Fire extinguisher		S
10	Safety devices	S	26	Display markings (SWL, tire pressure, insp. date, due date)		S
11	Battery and its connections	S	27	Full functional test		S
12	Hydraulic system & hoses and end fittings	S	28	Rated load test		S
13	Electrical system & Cables	S	29	Overload test		N/A
14	Cooling system	S	30	MPI fork blades, Date/Report No (Annually)		S
15	Steering function	S	31	Other Test (if applicable)		N/A
16	All controls levers function & symbols legible	S	32	General Condition		S
			33	Mast disassembly (Every 4 Years)		N/A

**Details of tools/equipment's used:**

**Findings/Critical Findings Report**

F/CF	No.	Remarks
--	30	FORK MPI DONE: 20/03/2025;K/3827/25/03/02

Verified by, Name &Signature: Infanso Oswin

Inspected by, Name & Signature: Anoop Thankachan



