الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

# MAGNETIC PARTICLE INSPECTION REPORT

| Date of Inspection: 22/01/2026 | Report number: MN/6867/26/01/01 | Job no: 6867 |
|---|---|---|

| Name and Address of owner for whom the thorough examination was made: | Address of premises at which the examination was made: |
|---|---|
| TRUCK OMAN LLC<br>SULTANATE OF OMAN | ADAM |

**Method: WET** **Material: Carbon Steel** **Test temperature: Ambient**
**Surface Condition: Acceptable** **Equipment: Permanent magnet Yoke**

**Area Inspected (tick the appropriate box):**

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [TOP SURFACE ONLY]

| | |
|---|---|
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 |

**DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:**

**FIFTH WHEEL**

**MAKE: JOST**

**TYPE: JSK39DV1-46**

**SERIAL NO: 34DD0300344C**

**CHASIS NO: LZZ8CLXD8RC591159**

**REG NO: 494 BA**

**FLEET NO:TO 2087**

**Qty: 1no.**

Date of Last MPI/ Cert No (If any): **VG/4692/25/08/01; 11/08/2025**

**Result of the above test:**

**MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION**

| Inspected by, Name & Signature: MIDHUN C S<br><br>Qualification: ASNT L2 | | Latest date by which next MPI must be carried out:<br><br>21/07/2026 |
|---|---|---|
| Name and address of employer of persons making and authenticating this report:<br><br>**Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS**<br>**P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.**<br>**lifting@safetyoman.com** | | SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED |