

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 13/08/2025	Report number: AT/4694/25/08/11	Job no: 4694
Name and Address of owner for whom the thorough examination was made: TRUCKOMAN LLC SULTANATE OF OMAN		Address of premises at which the examination was made: FAHUD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE]		
WHITE CONTRAST PAINT: MAGNAVIS WCP	MAGNETISING METHOD: WET SUSPENSION BLACK INK	
BLACK MAGNETIC INK: MAGNAFLUX 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:		
<p>FIFTH WHEEL</p> <p>Make: JOST</p> <p>Type: JSK39DV1-46</p> <p>Serial no: 34DD0300338C</p> <p>Chassis No: LZZ8CLXD3RC591165</p> <p>Reg no: 5493 DS</p> <p>FLEET NO: TO 2099</p>		
<p>Qty: 1 no</p> <p>Date of Last MPI/ Cert No (If any): MP/1190/25/02/009</p>		
<p>Result of the above test :</p> <p>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</p>		

Inspected by, Name & Signature: ANOOP		Latest date by which next MPI must be carried out: 12/02/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		