

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 28/06/2022	Report number: MP/48938/22/06/30	Job no: 48938
Name and Address of the Owner of the Equipment TRUCK OMAN (NORTH) SULTANATE OF OMAN		Address of premises at which the examination was made: HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	

Description and identification of the equipment:

MAIN HOOK MPI TEST OF MOBILE CRANE

Make : GROVE

Owner ID No. : TO-2551

Reg. no. : 6593 YS

Hook Block Serial No. : 12-4064

Qty: 1 no

Date of Last MPI/ Cert No(If any):29/06/2021 ; V/46970/10

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: After one year as per client requirement or at the discretion of the lifting inspector.
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

