

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---|
| Date of Inspection: 01/06/2023 | Report number: MP/51262/23/06/06 | Job no: 51262 |
| Name and Address of the Owner of the Equipment TRUCK OMAN (NORTH) SULTANATE OF OMAN | | Address of premises at which the examination was made: HAIMA |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>MAIN HOOK MPI TEST OF MOBILE CRANE</u> | | |
| Make : GROVE | | |
| Owner ID No. : TO-2551 | | |
| Reg. no. : 6593 YS | | |
| Hook Block Serial No. : 12-4064 | | |
| Qty: 1 no | | |
| Date of Last MPI/ Cert No(If any):28/06/2022;MP/48938 | | |
| Result of the above test : | | |
| MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|--|---|---|
| Inspected by, Name & Signature : Madhu Pillai |  | Latest date by which next MPI must be carried out: After one year as per client requirement or at the discretion of the lifting inspector. |
| Qualification : ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | |  |

