الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 22/01/2026	Report number: MN/6867/26/01/14	Job no: 6867

Name and Address of owner for whom the thorough examination was made:	Address of premises at which the examination was made:
TRUCK OMAN LLC SULTANATE OF OMAN	FAHUD

Method: WET **Material: Carbon Steel** **Test temperature: Ambient**
Surface Condition: Acceptable **Equipment: Permanent magnet Yoke**

Area Inspected (tick the appropriate box):

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [TOP SURFACE ONLY]

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:

FIFTH WHEEL

MAKE: JOST

TYPE: JSK39DV1-46

SERIAL NO: 34DD0100529C

CHASIS NO: LZZ8CLXD5RC591197

REG NO: 8397 MH

FLEET NO:TO 2131

Qty: 1no.

Date of Last MPI/ Cert No (If any): **VG/4692/25/08/05**

Result of the above test:

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION

Inspected by, Name & Signature: MIDHUN C S Qualification: ASNT L2		Latest date by which next MPI must be carried out: 21/07/2026
Name and address of employer of persons making and authenticating this report: **Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS** **P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.** **lifting@safetyoman.com**		SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED