

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 14/08/2025	Report number: AT/4694/25/08/18	Job no: 4694
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  FAHUD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:		
<p><u>FIFTH WHEEL</u></p> <p>MAKE: JOST</p> <p>TYPE: JSK39DV1-46</p> <p>SERIAL NO: 34DD0300348C</p> <p>CHASIS NO: LZZ8CLXD9RC591204</p> <p>REG NO: 5765 MA</p> <p>FLEET NO: TO 2134</p>		
Qty: 1no.		
Date of Last MPI/ Cert No (If any): MP/1190/25/02/023		
Result of the above test:		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature: ANOOP		Latest date by which next MPI must be carried out: 13/02/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		