



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

|                                                                                                                                                                                                                                                                        |                                                                                       |                                                                  |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|------------------------------------------------------------------|
| Date of Thorough Examination:<br>02/11/2025                                                                                                                                                                                                                            | Report number:<br>MN/5468/25/11/02                                                    | Job no:<br>5468                                                  |
| Name and Address of the Owner of the Equipment<br>TRUCK OMAN (CHSD)<br>SULTANATE OF OMAN                                                                                                                                                                               | Address of premises at which the examination was made:<br>FAHUD                       |                                                                  |
| Method: WET<br>Surface Condition: Acceptable                                                                                                                                                                                                                           | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke                            | Test temperature: Ambient                                        |
| Area Inspected (tick the appropriate box):<br><input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE ONLY]                                          |                                                                                       |                                                                  |
| WHITE CONTRAST PAINT: Magnavis WCP                                                                                                                                                                                                                                     | MAGNETISING METHOD: Wet suspension black ink                                          |                                                                  |
| BLACK MAGNETIC INK: Magnaflux 7HF                                                                                                                                                                                                                                      | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1                                |                                                                  |
| Description and identification of the equipment:<br><u>FIFTH WHEEL</u><br>Make: JOST<br>Type: JSK 38C<br>Chassis No: LZZ8CLDXRC654035<br>FLEET NO: TO 2151<br>REGISTRATION: 3262 HM<br>Qty: 1 no<br>Date of Last MPI/ Cert No (If any): MP/1213/25/05/002              |                                                                                       |                                                                  |
| Result of the above test:<br>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION                                                                                                                                              |                                                                                       |                                                                  |
| Inspected by, Name & Signature:<br>MIDHUN C S                                                                                                                                                                                                                          |    | Latest date by which next MPI must be carried out:<br>01/05/2026 |
| Qualification: ASNT L2                                                                                                                                                                                                                                                 |                                                                                       |                                                                  |
| Name and address of employer of persons making and authenticating this report:<br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a> |  |                                                                  |