

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/11/2025	Report number: MN/5468/25/11/14	Job no: 5468
Name and Address of the Owner of the Equipment  TRUCK OMAN (CHSD) SULTANATE OF OMAN		Address of premises at which the examination was made:  NIZWA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <u>FIFTH WHEEL</u>  Make: JOST  Type: JSK 38C  Chassis No: LZZ8CLXD6RC654047  FLEET NO: TO 2163  REGESTRATION: 3092 MD  Qty: 1 no		
Date of Last MPI/ Cert No (If any): MP/1213/25/05/14		
Result of the above test:  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature: MIDHUN CS		Latest date by which next MPI must be carried out: 01/05/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		