

الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---|
| Date of Thorough Examination: 22/01/2026 | Report number: MN/6869/26/01/23 | Job no: 6869 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN LLC SULTANATE OF OMAN | | Address of premises at which the examination was made: FAHUD |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: MAGNAVIS WCP | MAGNETISING METHOD: WET SUSPENSION BLACK INK | |
| BLACK MAGNETIC INK: MAGNAFLUX 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1 | |
| DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT: | | |
| <p>KING PIN AND FILLET WELD</p> <p>[I] SHAPED CYLINDRICAL KING PIN. TOP HEAD Ø114 mm INTERMEDIATE Ø89 mm BOTTOM HEAD Ø111 mm</p> <p>MAKE: JOST (3.5") TYPE: KZ14 CHASIS NO: ZFBT5021110000009 REG.NO.314 AK FLEET NO.: TO 2884</p> <p>Qty: 1nos</p> <p>Date of Last MPI/ Cert No (If any): VG/4696/25/08/032</p> <p>Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</p> | | |

| | | |
|--|--|--|
| Inspected by, Name & Signature: MIDHUN CS | | Latest date by which next MPI must be carried out: 21/07/2026 |
| Qualification: ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | | |