



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 22/01/2026	Report number: MN/6869/26/01/21	Job no: 6869
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN LLC SULTANATE OF OMAN	Address of premises at which the examination was made: FAHUD	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☒ Weldment areas ☒ Stress Areas ☐ Full Body ☐ Others		
WHITE CONTRAST PAINT: MAGNAVIS WCP	MAGNETISING METHOD: WET SUSPENSION BLACK INK	
BLACK MAGNETIC INK: MAGNAFLUX 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:		
<u>KING PIN AND FILLET WELD</u> [I] SHAPED CYLINDRICAL KING PIN. TOP HEAD Ø114 mm INTERMEDIATE Ø89 mm BOTTOM HEAD Ø111 mm MAKE: JOST (3.5") TYPE: KZ14 CHASIS NO: GIGF240058 REG.NO.1816 RK FLEET NO.: TO 2762 Qty: 1nos Date of Last MPI/ Cert No (If any): VG/4696/25/08/043		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature: MIDHUN CS		Latest date by which next MPI must be carried out: 21/07/2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		