

### MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 22/01/2026	Report number: MN/6869/26/01/51	Job no: 6869
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  RUSAYL
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: MAGNAVIS WCP	MAGNETISING METHOD: WET SUSPENSION BLACK INK	
BLACK MAGNETIC INK: MAGNAFLUX 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
<b>DESCRIPTION AND IDENTIFICATION OF THE EQUIPMENT:</b>		
<p><b>KING PIN AND FILLET WELD</b></p> <p>[I] SHAPED CYLINDRICAL KING PIN. TOP HEAD Ø114 mm INTERMEDIATE Ø89 mm BOTTOM HEAD Ø111 mm</p> <p>MAKE : JOST ( 3.5") TYPE: KZ14 CHASIS NO: GIGF240054 REG.NO.5806 BA FLEET NO.: TO 2775</p> <p>Qty: 1nos</p> <p>Date of Last MPI/ Cert No (If any): MP/1193/25/02/040</p> <p>Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</p>		

Inspected by, Name & Signature: MP/1193/25/02/040		Latest date by which next MPI must be carried out: 21/07/2026
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		