



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|---|--|
| Date of Through Examination: 05/03/2020 | Report number: MP/42145/20/03/23 | Job no: 42145 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN (NORTH) SULTANATE OF OMAN | Address of premises at which the examination was made: HAIMA | |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: KING PIN AND FILLET WELD Make : JOST (3.5") ID No. : 2663 Trailer Reg: 3942 YW [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1no. | | |
| Date of Last MPI/ Cert No(If any): 28/10/2018 MP/38530/18/10/06 | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by, Name & Signature : Qualification : ASNT L2 | Madhu Pillai | Latest date by which next MPI must be carried out: 06/03/2021 |
| Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com | | |