

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 07/01/2026	Report number: AT/6857/26/01/06	Job no: 6857
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  JIFNAIN PDO-YARD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <u>Fork Heel &amp; WELDS</u>  REG NO: 2084 LA OWNER ID: TO 2906 SERIAL NO: B12406890, 2406677A/CH2500X500		
Qty: 1 PAIR		
Date of Last MPI/ Cert No (If any): AT/4668/25/07/06		
Result of the above test:  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature: VIGNESH CT		Latest date by which next MPI must be carried out:  After One Year as Per Client Requirement Or At The Discretion Of Lifting Inspector
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		