

AN ISO / IEC 17020:2012 ACCREDITED INSPECTION BODY

CERTIFICATE OF TEST & THOROUGH VISUAL EXAMINATION OF FORKLIFT

Certificate No. : HITECH/TJN-2025-467/IC/051

Date of Inspection : 26/01/2026

Job Number : TJN-2025-467

Starting Time of Inspection: 11.05 AM

Name & Address of the Owner :		M/S.TRUCKOMAN EQUIPMENT RENTAL LLC,OMAN		
Make & Date of Manufacture :		SHANDONG LINGONG CONSTRUCTION MACHINERY / 2024		
Location of Inspection :		MUKHAIZNA, SULTANATE OF OMAN		
Ref. Standard / Procedure :		BS EN 474-3 / BS ISO 2330 / SP 2275 / OPAL GUIDELINE		
Registration No. & Owner No. :		8525 MD / TER 1565		
Model & Serial No. :		MODEL NO: L958F / SERIAL NO: VLGL958FPS0621118		
Running Hours :		2806 HOURS		
Date of previous inspection / Cert. No.:		31/07/2025,HITECH/TJN-2025-467/IC/014		
Date of next inspection :		26/07/2026		
Date of Previous Load Test Certificate No.:		31/07/2025,HITECH/TJN-2025-467/IC/014		
Date of Next Load Test / Performance Test Due on:		30/07/2026		
Availability OEM certificate :		IN SERVICE EQUIPMENT		
Availability of operations manual in cab :		YES, AVAILABLE		
Availability of load chart in cab :		YES, AVAILABLE		
Availability of daily check report :		YES, AVAILABLE		
Hitech Reference Work Instruction :		HITECH-LFT-WI-009-LAPFL-08		
Measuring equipments's used :		SL NO	TOOLS DESCRIPTION	CALIBRATION DUE
		1.	FORK CALIPER SL NO: HT-FWC-04	26/11/2026
		2.	MEASURING TAPE SL NO: 035206	02/12/2026
DESCRIPTION OF EQUIPMENT:	DIESEL POWERED HYDRAULIC ARTICULATED WHEEL LOADER OPERATED WITH SIDE SHIFTER - SWL IS 7000 Kgs @ 600MM LOAD CENTER.			

Description of Test: A Thorough visual and Functional test was carried out. Equipment was Operated and Observed thorough all of its motions. No Hydraulic Creep was Observed. Attachments: - Fork Arms SL No: 24098043 (LF 3500/600) Dimensions: 45 X 122 X 1070 (mm) Load Test Carried Out as per the Tabulated Column. Note: -Always refer to the manufacturer manual for safe operation of Forklift/ Wheel Loader. Examine the equipment before each use never exceed the rated capacity.	Test Load Applied (in Kgs)	Safe working load (in Kgs)
	N/A	7000 Kgs @ 600mm Load Centre

1. Conclusion: This is to certify that the above-mentioned lifting equipment were tested and thoroughly examined and found satisfactory at the time of inspection.

Date of Issue: 31/01/2026

Opal LEIB Number: LEIB373/303

Authorized Name: LAKSHMANDAS.M

Inspector Name: ANSON D'COSTA

Designation: TECHNICAL MANAGER (TPI)

Qualification: LIFTING INSPECTOR (NSL)

Authorized Signature:

Inspector Signature:



This certificate becomes invalid if any Alteration / Major Repair and modification is done. The inspection carried out as per regulation 9 of lifting operations and lifting equipment regulation 1998 (LOLER 98)-UK. This is to certify that the above signed HITECH Inspector, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformation or other defects. The liabilities & insurance as per HITECH Inspection Services LLC.

2. ANNEXURE OF CERTIFICATE OF TEST & THOROUGH VISUAL EXAMINATION OF FORKLIFT

Certificate No. : HITECH/TJN-2025-467/IC/051

Date of Inspection : 26/01/2026

Job Number : TJN-2025-467

Starting Time of Inspection: 11.05 AM

Status Legend: S-Satisfactory, NA-Not Applicable, F-Findings, CF-Critical Findings

Description	Status	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest, carriage	Satisfactory	
Forks and its extensions, Slide end Stopper, locks	Satisfactory	
Load chain and its assemblies	N/A	
Safety devices	Satisfactory	
Battery and its connections	Satisfactory	
Hydraulic system & hoses conditions	Satisfactory	
Boom Operation (Hydraulic sections, Cylinders, Hoses)	Satisfactory	
Electrical system & cables	Satisfactory	
Engine compartment	Satisfactory	
Cooling system / Fuel System Condition	Satisfactory	
Steering function	Satisfactory	
All controls lever's function & symbols legible	Satisfactory	
All gauges in cab	Satisfactory	
Overhead & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	Satisfactory	
Spark arrestor (if fitted)	Satisfactory	
Operator cab / wind shields / Mirrors	Satisfactory	
Horn, reverse alarm, rotating warning light	Satisfactory	
Light & indicators (Signal lights, Footbrake lights, Wipers)	Satisfactory	
Seat & seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
Functionally test (Drives Forward, Drives Backward, Front Hydraulic Functions, Stabilizers Function)	Satisfactory	
Rated Load test / Other test (if applicable)	N/A	
MPI forks blades, date/ report no.(Annually)	Satisfactory	HITECH/TJN-2025-467/MT-066,DT:31/07/2025
OEM Specification plate in place and legible	Satisfactory	
General condition (structural integrity/functionality)	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	Insp.date & next Insp.due date Needs to be marked

3. General comment: The equipment's is safe for its use within the limits specified, provided there is continuous maintenance applied and qualified operators employed. This Certificate covers only the existing configuration of the equipment at the time of examination. Any changes, alteration or modification shall require re-inspection or re-testing.

Date of Issue: 31/01/2026

Opal LEIB Number: LEIB373/303

Authorized Name: LAKSHMANDAS.M

Inspector Name: ANSON D'COSTA

Designation: TECHNICAL MANAGER (TPI)

Qualification: LIFTING INSPECTOR (NSL)

Authorized Signature:

Inspector Signature:



FULL MEMBER
 CERT. NO. 2839

This certificate becomes invalid if any Alteration / Major Repair and modification is done. The inspection carried out as per regulation 9 of lifting operations and lifting equipment regulation 1998 (LOLER 98)-UK. This is to certify that the above signed HITECH Inspector, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformation or other defects. The liabilities & insurance as per HITECH Inspection Services LLC.

