






TA'AZEEZ ENTERPRISES LLC


Po Box: 23, Pc: 103-AL Qurum North AL Ghoubra- Bowsheer
Sultanate Of Oman

MAGNETIC PARTICLE INSPECTION REPORT

Company Name and Address TRUCK OMAN NORTH LLC		Inspection Location: FAHUD RM
Certificate Number: MM.3296.02.26.26.01		Job No: 03296
Date of Thorough Examination: 26-02-2026	Time of Inspection: 07:00	Issue Date: 10-03-2026
Date of Previous MPI/ cert no: N/A		Date of Next Examination: 25.08.2026
Description : 3.5" FIFTH WHEEL MPI		
Description and identification of the equipment: REG NO: 8523 BA(TO 2142)		
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others (top surface)		
WHITE CONTRAST PAINT: ZCHEK WP		MAGNETISING METHOD: WET SUSPENSION BLACK INK
BLACK MAGNETIC INK: ZCHEK 9E Black		ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
TEST METHOD: WET		MATERIAL: CARBON STEEL
TEST TEMPERATURE: AMBIENT		SURFACE CONDITION: ACCEPTABLE
TEST EQUIPMENT: PERMANENT MAGNET YOKE		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by: MALIK MOHAMMED Qualifications: ASNT LEVEL II  Signature: Date: 10-03-2026	Company Stamp 
--	--

If any Alteration/Major Repair is made, this certificate is rendered invalid.
This is to confirm that the item listed above was examined by the undersigned competent representative in compliance with the aforementioned standard. The aforementioned objects were found to be free of faults, deformations, and other problems at the time of inspection. The equipment is suitable for its intended use within the permitted limits, and at the time of inspection, it was determined to be suitable for continued use, provided that continuous maintenance is applied, qualified operators are employed, and our comments and recommendations are put into practice.

The inspection certificate may not be republished in its entirety without the consent of the inspection body and the customer. Inspection is confined to the work ordered or lots inspected. Contact us at info@tis-om.com for certificate authenticity and clarification or scan QR code.	
--	---