



FIFTH WHEEL INSPECTION REPORT


REPORT NO.: UNITEC/FWI/M/26/105	INSPECTION DATE: 11-03-2026
Customer:	TRUCKOMAN LLC
Vehicle Registration Number:	6328 WA
Type of vehicle:	PRIME MOVER
CHASSIS No.:	LZZ8CLXD4TC722305
King Pin Size:	3.5"
NEXT DUE DATE:	10-09-2026

ITEMS DESCRIPTION:

Scope of Inspection	Make	TYPE/PART	Sr. Number
Fifth Wheel inspection of prime mover:	JOST	JSK 39 DV-46	----



Observation:

- # Above parameters are checked with MPI & Visual inspection and it found acceptable as per requirements.
- # At the time of inspection, the equipment was found satisfactory.
- # Examination Area – full body.



Results: **Accepted** / Rejected

I hereby declare that the above information is correct and that the equipment has been tested and examined in according to provisions & standard.

Inspected By:		 <p>Company Stamp</p>
NDT level II		
Sign		