





# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



## MAGNETIC PARTICLE INSPECTION REPORT

|  |   |                           |
|--|---|---------------------------|
| Date of Thorough Examination:<br>28.12.2025  | Report number:<br>AT6710.25.12.31                                   | Job no:<br>6710           |
| Name and Address of owner for whom the thorough examination was made:<br><br>TRUCK OMAN<br>SULTANATE OF OMAN   | Address of premises at which the examination was made:<br><br>HAIMA |                           |
| Method: WET<br>Surface Condition: Acceptable   | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke          | Test temperature: Ambient |
| Area Inspected (tick the appropriate box):<br><input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others   |   |                           |
| WHITE CONTRAST PAINT: Magnavis WCP   | MAGNETISING METHOD: Wet suspension black ink                        |                           |
| BLACK MAGNETIC INK: Magnaflux 7HF  | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1              |                           |
| Description and identification of the equipment:<br><b><u>KING PIN AND FILLET WELD</u></b><br><br>Make: JOST (3.5")<br>Trailer Reg: 8471 MR<br>Fleet no: TO-2653<br>[I] shaped cylindrical king pin.<br>Top head 114mmØ<br>Intermediate 89mmØ<br>Bottom head 111mmØ<br><br>Qty: 1nos<br><br>Date of Last MPI/ Cert No (If any): 10.07.2025 (AT4482.25.07.07) |   |                           |
| Result of the above test:<br><b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>   |   |                           |

|  |   |  |
|--|---|--|
| Inspected by Name & Signature:<br>Anoop Thankachan<br><br>Qualification: ASNT L2   |    | Latest date by which next MPI must be carried out:<br><br>27.06.2026 |
| Name and address of employer of persons making and authenticating this report:<br><br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a> |  |  |