



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 03/10/2019	Report number: A/40740/19/10/10	Job no: 40740
Name and Address of owner for whom the thorough examination was made:		Address of premises at which the examination was made:
TRUCK OMAN (NORTH) SULTANATE OF OMAN		HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):		
☒ Weldment areas ☒ Stress Areas ☐ Full Body ☐ Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<u>KING PIN AND FILLET WELD</u>		
Make : JOST (3.5")		
Trailer Reg: 8814 ML		
Fleet no. : TO-612		
[I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ		
Qty: 1no.		
Date of Last MPI/ Cert No(If any):N/A		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature :	Mohammed Anaz	Latest date by which next MPI must be carried out: 02/10/2020
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		