




MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 13/06/2018	Report number: O/37545/18/06/39	Job no: 37545
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: MARMUL	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☒ Weldment areas ☒ Stress Areas ☐ Full Body ☐ Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>KING PIN AND FILLET WELD</u> Make : JOST (3.5") Type : KZ 1016 Trailer Reg: 8803 MD Fleet No. : TS-610 [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1no. Date of Last MPI/ Cert No(If any): 26/06/2017 ; O/35013/17/06/27		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out: 12/06/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		