الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 20/11/2022	Report number: MP/49823/22/11/50	Job no: 49823

Name and Address of owner for whom the thorough examination was made:	Address of premises at which the examination was made:
TRUCK OMAN SULTANATE OF OMAN	SAFAH

Method: WET **Material: Carbon Steel** **Test temperature: Ambient**
Surface Condition: Acceptable **Equipment: Permanent magnet Yoke**

Area Inspected (tick the appropriate box):

☑ Weldment areas ☑ Stress Areas ☐ Full Body ☐ Others

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

KING PIN AND FILLET WELD
Make : JOST (3.5")

Trailer Reg: 7237 MA

Fleet No: TS-614

[I] shaped cylindrical king pin.
Top head 114mmØ
Intermediate 89mmØ
Bottom head 111mmØ

Qty: 1 no

Date of Last MPI/ Cert No(If any): 04/10/2021; MP/45998/21/10/07

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Koshy Mathew Qualification : ASNT L2	Koshy	Latest date by which next MPI must be carried out: 19/11/2023

Name and address of employer of persons making and authenticating this report:

Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS
P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.
lifting@safetyoman.com

SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED