



MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 02/06/2023	Report number: MP/51262/23/06/10	Job no: 51262
Name and Address of the Owner of the Equipment TRUCK OMAN (NORTH) SULTANATE OF OMAN		Address of premises at which the examination was made: HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	

Description and identification of the equipment:

FORK TOP & BOTTOM HOOK & HEELS

Make : CATERPILLAR

Fleet No. : TO-2520

Reg. No. : 3585 HW

Fork Dimensions: LXWXH – 1270 X 120 X 800 mm

FORK S/N . 2729574 A- L 8(R)

FORK S/N . 2736431- L8 – (L)

Qty: 1 no

Date of Last MPI/ Cert No(If any): 28/06/2022;MP/48938/22/036/08

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 01/12/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

