



CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: MP/40157/19/04/01

Date of Inspection: 03/04/2019

Name and Address of the Owner:	TRUCK OMAN (NORTH)
Maker & Date of Manufacture:	CAT ; 2011
Place of Inspection:	HAIMA
Ref. Standard:	BS ISO 2330/BS EN 474-3/SP 2275
Registration No. & Owner No.:	3585 HW ; TO-2520
Model No. and Serial No.:	930 H ; DHC03027
Running hours:	13298 hrs.
Manufacturer's documentation:	OK
Date of Previous inspection / cert no:	08/10/2018 ; MP/38516
Date of Next inspection:	02/10/2019
Date of Previous load test / cert no:	26/04/2017 ; A/34076
Date of Next load test:	25/04/2021
Availability of operations manual in cabin:	OK
Availability of daily check report:	OK

Description :

Diesel powered hydraulic articulated Wheel Loader with fork SWL : 6.3 t @ 600mm.

Test carried out according to tabulated column

Description of test: Visual inspection, Functional test & Performance test carried out. Max. Lifting Height : 3800mm Hydraulic creep : Nil	Test load applied In kgs	S.W.L In kgs
	6.3 t	6.3 t

Conclusion: Fit for its intended use at the time of inspection.

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin





Annexure of certificate of test & thorough examination

Certificate no: MP/40157/19/04/01

Inspection date: 03/04/2019

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest , carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	N/A	
Side rollers and roll over cage	N/A	
Safety devices	Satisfactory	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & Cables	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls levers function & symbols legible	Satisfactory	
Capacity plate in place and legible	Satisfactory	
All gauges in cab	Satisfactory	
Over head & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	N/A	
Horn, reverse alarm, rotating warning light	Satisfactory	
Lights & indicators	Satisfactory	
Seat and seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
MPI fork blades, date / report nr. (annually)	Satisfactory	03/04/2019 ; MP/40157/19/04/02
Mast disassembly (every 4 years)	N/A	
General condition	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	
Details of tools/equipments used: Measuring tape (STS-LD-75) ; Vernier Caliper (STS-LD-65)		

General comments: NONE

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

