



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272, Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

ENGINEERS WORK REPORT/ TIME SHEET

M/S Truckman north Address: Job Requestor: Jewel Sharma Job Location: Safah	Work No: 44237 Job No: LPO/Ref No:
--	--

Description of Job Performed:

165, 166, 167, 774, 776, 2306, 2310, 202, 213, 567, 579, 580, 582,
601, 602, 603, 605, 607, 608, 903, 1004, 1010, 1016, 1017, 2301, 2302, 2303, 2304, 2305,
525, 600, 1047, 1048, 1049, 1052, 2034, 2035, 2038, 2047, 2048, 2049, 2050, 2054,
2055, 522, 524, 525, 568, 569 - (Fifth wheels MPI)



239, 601, 604, 617, 1834, 612, 294, 294, 2658, 615, 383, 390, 391,
392, 1604, 202, 212, 298, 271, 279, 2886, 299, 201, 209, 228, 229, 293, 440, 449, 208,
1850, 2656, 2666. (King Pin)

790, 166, 2301, 2041, 905, 167, 903 (Winch)
↓
HIAB.
+ 12h's.

Tools Used (Load Cell/Test Weights etc): MIT + MPI kit.

Date Started: 23/8/20 Date Completed: 24/8/20 No. of Days: 2 Kms Driven:	Travelling Time: 5 hrs Originated From: MCT Total Cost: 165 x 2 = 330 Ro/-
---	--

The above mentioned work has been completed to our satisfaction and details confirmed as per the report.

Signature:  Customer Representative (Name): SHIBIN VARHESE Contact No: 97759898	Signature:  Name of Engineer: VISEESH RAVI Contact No: 94304246
--	---