



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|--|--|
| Date of Thorough Examination: 31/12/2018 | Report number: MP/39026/18/12/10 | Job no: 39026 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN NORTH SULTANATE OF OMAN | | Address of premises at which the examination was made: HAIMA |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: KING PIN AND FILLET WELD Make : JOST (3.5") ID: TO591 Trailer Reg:4865Y.R [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ | | |
| Qty: 1 nos | | |
| Date of Last MPI/ Cert No(If any):N/A | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by, Name & Signature : Qualification : ASNT L2 | MADHU PILLAI | Latest date by which next MPI must be carried out: 30/12/2019 |
| Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com | | |