



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 26.02.2026	Report number: AT6748.26.02.48	Job no: 6748
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made:  HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>KING PIN AND FILLET WELD</u>  Make : JOST ( 3.5") Type: KZ14 Reg No: 4767 YR Fleet No: TO 590 [I] shaped cylindrical king pin. Top head Ø114 mm Intermediate Ø89 mm Bottom head Ø111 mm  Qty: 1nos  Date of Last MPI/ Cert No( If any): 01.10.2025 (AT5222.25.10.44)		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Anoop Thankachan  Qualification : ASNT L2		Latest date by which next MPI must be carried out:  25.08.2026
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		