

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 03/07/2023	Report number: MP/51274/23/06/01	Job no: 51274
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: SAFAH	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>CRANE HOOK MPI</u> Owner ID No.: PLM 1486 Crane Reg No: 6594 YS HOOK S/NO: 12/7177 Qty: 1no.		
Date of Last MPI/ Cert No(If any): 03/08/2022;MP/48950 Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature: Madhu Pillai		Latest date by which next MPI must be carried out: After one year or as per the discretion of Lifting Inspector
Qualification: ASNT L2 Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

