



# **CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF MOBILE CRANE**

**Certificate No: MP/37723/18/08/01**

**Date of Inspection: 31/08/2018**

Name and Address of the Owner:	<b>TRUCK OMAN NORTH</b>			
Maker & Date of Manufacture:	GROVE – 2012			
Place of Inspection:	HAIMA BASE			
Ref. Standard:	<b>BS 7121-2-3; PR 1708</b>			
Registration No.& Owner No.:	6594 YS ; PLM-1486			
Model and Serial No.:	RT-765E-2 ; 232672			
Nr. of running hours and/or km read out:	08019 hrs.			
Manufacturer's documentation:	Yes			
Date of Previous inspection / cert. no:	11/07/2017 ; MP/34793/17/07/01			
Date of Next inspection :	30/07/2019			
Date of Previous load test/ cert. no:	05/07/2016 ; MP/32076/16/07/1			
Date of Next load test:	04/07/2020			
Availability of operations manual in cab:	Yes			
Load Chart in cab:	Yes			
Accessories certificates:	Yes			
Availability of daily check report:	Yes			
Maintenance records / major repairs carried out:	Yes			
Description of Crane: <b>Diesel powered, Hydraulically operated, telescopic boom rough terrain mobile crane</b> Max.capacity of crane 60 tonnes at 10.9m boom length and 3m radius and using 19mm steel wire rope at 10falls.				
<b>Test carried out according to tabulated column</b>				
<b>Description of test: (configuration of the crane at the time of inspection)</b>  No. of falls: 8  Main hook block S.N: 12-7177  Main hook capacity: 60mTon  Aux.hook S.N: N/F  Aux.hook capacity: N/F  Wire rope certificate no: 1\2012 411-306983	Boom length	Radius	Test load	Safe working load
	(m)	(m)	Tonnes	Tonnes
	10.9m	4.5	---	42.8 t
	12.2m	7m	---	28.30 t
	18.4m	16m	6.7 t	6.755 t
	33.5m	30m	---	2.135 t
<b>Conclusion: Fit for its intended use at the time of inspection.</b>				

# Annexure of certificate of test & thorough examination of mobile crane

**Certificate No: MP/37723/18/08/01**

**Date of Inspection: 31/08/2018**

Description	Condition	Remarks
Safe load indicator/calibration verified	✓	
Level indicator / Angle indicator	✓	
Telescopic boom extensions/Boompads/Rope guides	✓	
Lattice boom sections/Connecting pins/Boom back stops	N/A	
Pendant ropes	N/A	
Fly Jib / Luffing jib/ Derricking interlocksecurity	N/F	Stowed
Main hoist winch/ Hoist drum / Correct spooling	✓	
Main hoist wire ropes and termination	✓	
Auxiliary hoist winch/ Hoist drum / Correct spooling	N/F	
Auxiliary wire ropes and termination	N/F	
Counterweight and its locking mechanism	✓	
Access ladders/Walkways/Hand & guard rails	✓	
Outriggers/ beams / jacks / pads	✓	
Tires / rims / wheel bolts	✓	
Crawler Tracks/Track shoe	N/A	
Swing machinery /Swing alarm / Swing lock	✓	
Swingbearing/ -wear / report	N/A	n/a for verification
Hook block system/Safety catch	✓	
Hook MPI, certificate no (Required every 4 yrs)	✓	18/8/2014 ; A/27438/14/8/2
Sheaves(Boom & Hook)	✓	
Operator cab/ Control levers /Wind shields/Mirrors	✓	
Anti 2 block /over lower/ boom cut off /over load cut off limit switches / Slack rope limiter(if fitted)	✓	
Proximity switches	N/A	
All fasteners /Bolts / Safety pins	✓	
Electrical System	✓	
Hydraulic System	✓	
Caution rotary light	✓	
Reverse Horn / Light	✓	
Fire extinguisher	✓	13/09/2018
Anemometer(if fitted or hand held)	N/A	
General condition (structural integrity/functionality)	✓	
Display marking (SWL/tyre pressure/ insp.date/due date)	✓	

General comments: Nil

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature: Madhu Pillai



