



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 23/08/2020	Report number: VI/44237/20/08/70	Job no: 44237
Name and Address of the Owner of the Equipment TRUCK OMAN - NORTH SULTANATE OF OMAN	Address of premises at which the examination was made: SAFAH	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☒ Weldment areas ☒ Stress Areas ☐ Full Body ☐ Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: KING PIN AND FILLET WELD Make : JOST (3.5") Type : KZ 14 Trailer Reg: 8173 HW / PLM 279 [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1nos Date of Last MPI/ Cert No(If any):N/A		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Vijeesh Ravi Qualification : ASNT L2		Latest date by which next MPI must be carried out: 22/08/2021
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		