





الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|---|--|
| Date of Thorough Examination: 27.12.2025 | Report number: AT6710.25.12.02 | Job no: 6710 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN | Address of premises at which the examination was made: HAIMA | |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1 | |
| Description and identification of the equipment: <u>KING PIN AND FILLET WELD</u> Make: JOST (3.5") Trailer Reg: 1505 RK Fleet no: TO-1603 [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1nos Date of Last MPI/ Cert No (If any): 10.07.2025 (AT4482.25.07.02) | | |
| Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by Name & Signature: Anoop Thankachan Qualification: ASNT L2 |  | Latest date by which next MPI must be carried out: 26.06.2026 |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com |  | |