

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 09.07.2025	Report number: AT4482.25.07.38	Job no: 4482
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709 ,AWS D1.1	
Description and identification of the equipment: King Pin and Fillet Weld Make: JOST (3.5") Id No: TO 2684 Trailer Reg: 6095 MA [I] shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ Qty: 1nos Date of Last MPI/ Cert No (If any): 29/01/2025 (MP/1185/25)		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by Name & Signature: Anoop Thankachan		Latest date by which next MPI must be carried out: 08.01.2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		